

General Environmental Incident Summary

Incident: 4044 **Date/Time Notice:** 3/19/2016 2340 **DEM Incident No:**
Responsible Party: Nuverra
Date Incident: 3/19/2016 **Time Incident:** 1200 **Duration:**
County: Williams **Twp:** 154 **Rng:** 95 **Sec:** 22 **Qtr:**
Lat: 48.15190 **Long:** -102.89160 **Method:** Interpolation from map
Location Description: Hess Hawkeye Pipeline - North River Crossing (Lat: 48.1518951 Long: -102.8916083)

Submitted By: Alex Beach **Affiliation:**
Address: 3015 16TH ST SW STE 20
City: Minot **State:** ND **Zip:**

Received By:

Contact Person:

3711 4th Avenue Northeast
Watford City, ND

Distance Nearest Occupied Building: 0.5 Miles **Release Contained:** No

Type of Incident: Vac Truck Release

Description of Released Contaminant: Refined Oil from Vac Truck

Volume Spilled: 0.25 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

A Nuverra vac truck operator was transferring liquids from a tank to the vac truck. During the transfer, the vac truck vented approximately one quart of oil onto the ground impacting an estimated 2' by 5' area.

Risk Evaluation:

There were no immediate risks to report.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

There were no additional impacts to report. All of the impacted material was cleaned up.

Action Taken or Planned:

The Nuverra dispatch office was contacted. The spill was cleaned up by someone certified in 40 hour Hazwoper. The Nuverra EHS representative has supplied the vac truck operators with small secondary containment systems to prevent similar spills in the future.

Wastes Disposal Location: The waste will be disposed of at an approved waste disposal facility.

Agencies Involved:

Updates

Date: 3/19/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 3/22/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived on location at 11:00. East wind 15-20 mph, 28 degrees F, cloudy. Spoke with a contractor on site who led me to a pipe that Nuverra would occasionally hook up to and remove excess condensate from the lines. It appeared that an area below the piping and around the containment box had been removed and replaced with new soil/gravel. Will need to follow up with Hess contact to determine if location of observation was correct. Photos were taken of the new soil/scoria area. More follow-up needed.